



SCUBA CLINIC CO., LTD
 75/125-7 Soi Chaofa 47 West Chaofa Rd, Chalong
 Muang Phuket 83100. **Email:** info@scuba-clinic.com
Tel: 083 542 9205. **Website:** www.scuba-clinic.com

Regulator Refurbishment Certificate

Work Order:

10025 -2

Client's name: XXXXXXXXXXXXXXXXXXXX
 Address: [Redacted]
 Phone number: [Redacted]
 Email: [Redacted]
 Date In: 6 Feb 14

	1st	2nd	Octo
Make:	Scubapro	Scubapro	Scubapro
Model:	MK25	A700	C200
Serial #:	1218702179	1218702179	1226203854

Reported Faults (if any): 0
 Owner's requests: [Redacted]

Initial observations/remarks: Missing HP port plug. Non original mouthpiece 2nd stage. Slight ding on the knob retainer of the DIN fitting of the 1st stage. Minor scratches on metal casing A700. Inhalation resistance above manufacturers' specifications.

The above items of equipment have been refurbished in accordance with the manufacturer's requirements and in accordance with ASSET CP1 and CP3 as appropriate.

Final Test:		LP (500 PSI)	HP (3000 PSI)
Static IP lockup - including drift LP:	PSI	135	135
Static IP drift only (+/-) LP:	PSI		
IP @ full purge LP (*):	PSI	115	122
Static cracking inhalation effort 2nd stage LP:	"H ₂ O	1.2	1.2
Static cracking inhalation effort octopus LP:	"H ₂ O	1.5	1.5
A.I.R. @ 25 SCFM (*) or:	"H ₂ O		
Maximum flow @ 2.5" H ₂ O (*):	SCFM		

Initial Test - for reference -:	
LP (500 PSI)	HP (3000 PSI)
135	130
80	120
2	2.1
2.2	2.4

Hose condition satisfactory **yes** O2 cleaned **n/a**
 Adjusted to manufacturer's specifications **yes** max O2 **21** %
 BCD LP hose refurbished **yes**
 Dry suit hose refurbished **n/a** Leak tested **yes**
 HP hose and swivel refurbished **yes**
 Pressure gauge in accordance with EN 250 **yes**
 Pressure gauge replacement recommended **yes**

Service Notes: Filter slightly green (corrosion). Found sand in octo, pre-dive/dive control knob moved with difficulty, part 11.360.106 or jam nut damaged (thread damage on first thread towards case) likely due to overtightening (plastic part). HP port plug fitted where missing.

Parts Used:	Part #	Description	Qty
-------------	--------	-------------	-----

10.750.045	kit mk25	1
11.700.045	kit a700	1
11.361.045	kit c200/c300	1
O.N011/75	o-ring nitrile 011/75	1
O.N003/90	o-ring nitrile 003/90	2
0	HP port plug	1
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0
0	0	0

Recommendations:

Replace jam nut on octo (part 11.360.106) during next service.

We have carefully refurbished your equipment. In the unlikely event that you experience a problem with it, during the next thirty days, please return to us immediately. Any remedial work, arising from the work carried out by us will be corrected free of charge. Additional parts or labour that did not form part of the original refurbishment or are judged to be the result of damage, tampering or misuse will be charged to you. This warranty does not affect your statutory rights.

Technician's Signature:

L. Maertens ASSET# CT1105

Date:

6 Feb 14

(*) Optional